

NAVISTAR, INC

DEFECT INFORMATION REPORT

TO: Manager
Engine Programs Group (6405J)
Environmental Protection Agency
1200 Pennsylvania Avenue, NW
Washington, DC 20460

REPORT ID: 15-I6-12000563_01
Revision.: -
Ref. Invest.: -
Ref. AFC: -
Ref. VERR: -

FROM: Dave Polivka
Emissions Certification and Compliance
Navistar, Inc.
2601 Navistar Dr.
Lisle, IL 60532

DATE : March 04, 2015


The following Defect Information Report is submitted in accordance with 40 CFR §1068.501.

[40 CFR §1068.501(d)(1)] MANUFACTURER CONTACT INFORMATION

Dave Polivka
Emissions Certification and Compliance
Navistar, Inc.
2601 Navistar Dr.
Lisle, IL 60532
(331)-332-5662


[40 CFR §1068.501(d)(2)] DEFECT DESCRIPTION

This report addresses a design defect in the electronic / hydraulic unit injector. The injector contains an “open” coil and “close” coil as seen below. The coils move a spool valve back and forth, which admits high pressure oil to an intensifier piston, causing a fuel injection event.




Both coils have a “high side” and “low side” solder connection which attaches the injector wiring to the coils. The “high side” solder joint in the close coil will occasionally increase in resistance. This may be due to manufacturing issues or contamination from engine oil. Once the resistance increases, localized Joule heating causes melted solder and copper wire to create a short circuit to the injector body (ground). This is commonly referred to as a “HiPot” failure. Due to the control system design, a HiPot failure will disable 3 injectors and set appropriate diagnostic codes.

Below is a sectioned close coil illustrating a typical HiPot failure. The charred area between the red lines is where the solder has shorted the terminal to the injector body.



High side pin of injector coil becomes shorted to ground.

Below is an x-ray of another failed close coil.



Solder joint is completely melted

- Wires are completely gone

This failure mode increased from less than 1% of injector failures to ~ 45% when a design change to the fuel pressure/oil pressure intensification ratio was made. The ratio was increased from 7.6 / 1 to 10 / 1. This change required additional injector modifications to allow for higher oil demands including a longer close coil energize duration. The duration was increased from 1.0 mS to 1.5 mS for all engine operation even though it was only required for high fuel flow and / or extreme cold or hot oil operation.

A software modification has been designed and calibrated which will reduce the close coil on time to 1.2 mS during engine operation when 1.5 mS is not required while automatically returning to 1.5 mS when required.

[40 CFR §1068.501(d)(3)] DESCRIPTION OF VEHICLES/ENGINES AFFECTED

| <u>Engine Family Name</u> | <u>Model Year</u> | <u>Engine Model</u> | <u>Engine Plant Ship Dates</u> |
|---------------------------|-------------------|---------------------|--------------------------------|
| ANVXH04660GA | 2010 | MaxxForce DT | 2010 |
| BNVXH04660GA | 2011 | MaxxForce DT | 2011 |
| BNVXH04660GC | 2011 | MaxxForce DT | 2011 |
| BNVXH05700GA | 2011 | MaxxForce 9/10 | 2011 |
| CNVXH04660GA | 2012 | MaxxForce DT | 2012 |
| CNVXH04660GB | 2012 | MaxxForce DT | 2012 |
| CNVXH05700GA | 2012 | MaxxForce 9/10 | 2012 |
| CNVXH05700GC | 2012 | MaxxForce 9/10 | 2012 |
| DNVXH04660GA | 2013 | MaxxForce DT | 2013 |
| DNVXH04660GB | 2013 | MaxxForce DT | 2013 |
| DNVXH05700GA | 2013 | MaxxForce 9/10 | 2013 |
| ENVXH05700GA | 2014 | MaxxForce 9/10 | 2014 |
| ENVXH05700SA | 2014 | N 9/10 | 2014 |
| FNVXH05700GA | 2015 | MaxxForce 9/10 | 2015 |
| FNVXH05700SA | 2015 | N 9/10 | 2015 |

[40 CFR §1068.501(d)(4)] NUMBER OF ENGINES ESTIMATED TO HAVE DEFECT

Failure rates are based on injector failures at 40 months in service with HiPot failures being 45% of injector failures and one failure per engine. Model years 2013, 2014, and 2015 expected to match 2012.

| <u>Engine Family Name</u> | <u>Number of Engines</u> <u>Affected</u> | <u>Total Production</u> | <u>Percent of Family Affected</u> |
|---------------------------|---|-------------------------|-----------------------------------|
| ANVXH04660GA | 950 | 12,947 | 7.3% |
| BNVXH04660GA | 1,480 | 12,002 | 12.3% |
| BNVXH04660GC | 2,012 | 16,317 | 12.3% |
| BNVXH05700GA | 910 | 7,382 | 12.3% |
| CNVXH04660GA | 863 | 9,831 | 8.8% |
| CNVXH04660GB | 1,369 | 15,608 | 8.8% |
| CNVXH05700GA | 328 | 3,735 | 8.8% |
| CNVXH05700GC | 25 | 285 | 8.8% |
| DNVXH04660GA | 554 | 6,300 | 8.8% |
| DNVXH04660GB | 799 | 9,084 | 8.8% |
| DNVXH05700GA | 251 | 2,847 | 8.8% |
| ENVXH05700GA | 1000 | 11,358 | 8.8% |
| FNVXH05700GA | 15 | 172 | 8.8% |

[40 CFR §1068.501(d)(5)] EVALUATION OF EMISSIONS IMPACT

The emissions impact of a HiPot failure is unknown.

If the injector spool valve fails to close, that one injection event will receive the maximum fuel quantity available but the next commanded injection event will not occur as there will be no fuel to inject. The intensifier piston would have never returned to its original position. The ECM will store a trouble code and light a lamp. Due to shared circuitry, one failed injector causes one of two high side drivers to turn off deactivating a total of three injectors. Engine operation on three of six cylinders will be unacceptable.

[40 CFR §1068.501 (d)(6)] ANTICIPATED MANUFACTURER FOLLOW-UP

Navistar intends to perform a voluntary emissions recall to reflash ECM's with calibrations containing updated close coil on time software. Due to the number of engines the recall will be performed in stages.

SIGNED: Dave Polivka
Emissions Certification and Compliance